



Screw Selection Guide

Head Types *(measure length from surface of material to screw tip)*



Head Sizes

	#4	#5	#6	#7	#8	#9	#10	#14
Flat Head	0.225"	0.252"	0.255"	0.295"	0.332"	0.335"	0.385"	0.491"
Oval Head		0.252"						
Pan Head			0.270"	0.296"	0.322"		0.373"	
Pocket Hole/Face Frame			Modified	Modified				
Truss Head			0.260"		0.384"			
Standard Washer Head					0.375"		0.500"	
Large Washer Head					0.500"			



Drives

PHILLIPS	PHILLIPS SLOTTED COMBO	POZI	POZI SLOTTED COMBO	SQUARE	PHILLIPS SQUARE COMBO	HEX
<i>Most common in wood applications</i>	<i>Popular on truss head machine screws</i>	<i>Allows tight engagement, prevents stripping</i>	<i>Found on 2-piece connectors</i>	<i>Popular in hand-driven applications</i>	<i>Allows tight engagement, prevents stripping</i>	<i>Found on drivers and draw bolts</i>
Use Phillips bit to drive	Use Phillips or Flat bit to remove		Use Pozi or Flat bit to remove	Use Pozi bit to drive	Use Square or Combo bit to drive	
				Allows tight engagement, prevents stripping	Use Square, Combo, or Phillips bit to remove	

